



REPORT NUMBER

012878

DATE OF ISSUE

19-07-2018

Client

SafeStand Ltd Unit 6 Fourth Way Wembley Middlesex HA9 0LH

Customer order No

SAS00382

Testing of

3 samples 1200L mk6 2.2m 1200L mk 5 2.2m 800/5L 1340mm

to BS1139 Part 4 1982, requested bay loading uniformly distributed and temporary edge protection test in accordance with BS EN13374 load test values.

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House

Trading Address: Lloyds British

16 The Parks

Unit 1 kings Hill Business Park **Darlaston Road**

Tel: 0121 506 4620 Email: Sales@Lloydsbritish.com

Newton-Le-Willows Merseyside WA12 0JQ

Wednesbury WS10 7SH

www.lloydsbritish.com

Registered Office: Chase House, 16 The Parks, Newton – Le – Willows, Merseyside WA12 0JQ Registered in England and Wales under no 6847930 VAT Reg No GB 151 6295 70



Page 1 of 8

TABLE OF CONTENTS

9.0

1.0	Test Objective
2.0	Name of test house
3.0	Accreditation Reference
4.0	Date of test
5.0	Witness details
6.0	Description of samples tested
7.0	Test type
8.0	Equipment and calibration

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House

Trading Address: Lloyds British

Test data

16 The Parks

Unit 1 kings Hill Business Park **Darlaston Road**

Email: Sales@Lloydsbritish.com

Newton-Le-Willows Merseyside WA12 OJQ

Wednesbury WS10 7SH

www.lloydsbritish.com

Tel: 0121 506 4620

Registered Office: Chase House, 16 The Parks, Newton – Le – Willows, Merseyside WA12 0JQ Registered in England and Wales under no 6847930 VAT Reg No GB 151 6295 70



Page 2 of 8

1.0 Test Objective

To ascertain the suitability of the samples supplied, for load testing to BS1139 Part 4 1982. UDL upon two trestle platform at 5 board wide x 1150mm. Temporary hand rail test in accordance with loads specified in BSEN13374:2003

2.0 Name Of Test House

Lloyds British Unit 1 Kings Hill Business Park Darlaston Road Wednesbury WS10 7SH

3.0 Accreditation Reference

ISO 9001: 2008

4.0 Date Of Test

21/06/18

5.0 Witness Details

Mr B O'Driscoll

6.0 Description of items tested.

1200L MK6 2.2m 1200L MK5 2.2m 800/5L MK21340mm

7.0 Test Type

16 The Parks

Newton-Le-Willows

Load Testing of 3 samples in accordance with BS1139 part 4 1982 test specifications. Requested UDL test upon 2 trestle 5 board system at 1150mm length nominal. Handrail/guard rail subject to load specifications of BSEN13374:2003

8.0 Equipment & Calibration

Calibrated test weights
Hydraulic pump and ram back calibrated.
Calibrated tensile load link and pulling equipment.
Measuring device range 0.5mm to 30mm.

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House Trading Address: Lloyds British

Unit 1 kings Hill Business Park

Darlaston Road Email : Sales@Lloydsbritish.com
Wednesbury WS10 7SH www.lloydsbritish.com

Tel: 0121 506 4620

Merseyside WA12 0JQ Wednesbury WS10 7SH

Registered Office: Chase House, 16 The Parks, Newton – Le – Willows, Merseyside WA12 0JQ

Registered in England and Wales under no 6847930 VAT Reg No GB 151 6295 70



Page 3 of 8

9.0 **Test Data**



BS1139 Part 4 1982 requires that each stand should be able to withstand 2 ½ times the stated SWL without failure at 1°30 out of plumb without ultimate failure. The test load was applied as per the code, each load point to be 75mm at 1/4 span in from each end.

Each sample subject to test was tested at maximum height. All failures as per test photograph.

Sample	Model	Load achieved
1	1200L MK6	3000kgs
2	1200L MK5	3000kg
3	800/5L MK2	3000kg

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House

Trading Address: Lloyds British

16 The Parks

Unit 1 kings Hill Business Park

Tel: 0121 506 4620

Newton-Le-Willows Merseyside WA12 0JQ **Darlaston Road** Wednesbury WS10 7SH Email: Sales@Lloydsbritish.com www.lloydsbritish.com



Page 4 of 8

Sample test results BS1139-4

Test upon two trestle system at maximum extension UDL



Sample	Model	Height	Load achieved	Static/Live	Sustained
				Load	Load
1	1200L MK6	2.2mtr	5000kg	YES	YES
2	1200L MK5	2.2mtr	5000kg	YES	YES
3	800/5L MK2	1340mm	5000kg	YES	YES

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House

Trading Address: Lloyds British

16 The Parks

Unit 1 kings Hill Business Park

Tel: 0121 506 4620

Newton-Le-Willows Merseyside WA12 0JQ **Darlaston Road** Wednesbury WS10 7SH Email: Sales@Lloydsbritish.com www.lloydsbritish.com

Registered Office: Chase House, 16 The Parks, Newton – Le – Willows, Merseyside WA12 0JQ Registered in England and Wales under no 6847930 VAT Reg No GB 151 6295 70



Page 5 of 8


9.1 Test data

Testing of temporary hand rail system in accordance with BSEN13374:2003

TEST 1: STATIC LOAD TEST, SECTION 6.3 TO 6.3.3 TEST LOAD DIAGRAM:

Each static load case was applied in turn as per BS EN 13374: 2004 section 6.3 static load.

DIAGRAM 1: SAMPLE ERECTION:



9.1Test Data

RESULTS: TABLE 1: Mid point of handrail

TEST	LOAD APPLIED	DEFLECTION	PERMANENT SET
А	0.3kN	13mm	None
В	0.3kN	8mm	None
С	0.2kN	0mm	None
D	1.25kN	9mm	None
E	1.25kN	7mm	None
F	1.25kN	0mm	None

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House

Trading Address:

Lloyds British

16 The Parks

Unit 1 kings Hill Business Park

Tel: 0121 506 4620

Newton-Le-Willows

Darlaston Road

Email: Sales@Lloydsbritish.com

Merseyside WA12 0JQ

Wednesbury WS10 7SH

www.lloydsbritish.com


Registered Office: Chase House, 16 The Parks, Newton – Le – Willows, Merseyside WA12 0JQ

Registered in England and Wales under no 6847930 VAT Reg No GB 151 6295 70



TEST 2: LOAD PARALLEL TO THE GUARD RAIL

The edge protection was subjected to a 0.2 KN force horizontally at the most obvious point. The assembly should be capable of withstanding the request force.




The sample: Withstood a force of 0.2 KN horizontally - 12mm deflection no permanent set

TEST 3: ACCIDENTAL LOADING. 6.3.6

Any guard rail, intermediate guard or toe board shall be capable of resisting a downward force / point load of 1.25 KN on a 100 mm length.

The load was applied using a calibrated weight in each load case. The load was applied at the most unfavorable position in a downward direction of ± 10 degrees from the vertical section 6.3.6. All samples withstood the 1.25 KN force applied as per accidental loading.



All above testing withstood the requested load applications as requested by client.

See test D,E,F FOR DEFLECTIONS

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House

Trading Address:

Lloyds British

16 The Parks

Unit 1 kings Hill Business Park

Tel: 0121 506 4620

Newton-Le-Willows Merseyside WA12 0JQ

Darlaston Road Wednesbury WS10 7SH Email: Sales@Lloydsbritish.com www.lloydsbritish.com

Registered Office: Chase House, 16 The Parks, Newton – Le – Willows, Merseyside WA12 0JQ

Registered in England and Wales under no 6847930 VAT Reg No GB 151 6295 70



Test Conducted By: M.Gee and R.Atkinson Test and examination Engineer

Report Reviewed By:

Mr D.P.Marson



.....Lloyds British engineering manager

Test Conducted on behalf of

SafeStand Ltd 38a Fourth Way Wembley Middlesex HA9 0LH

Lloyds British is a trading division of Speedy Asset Services Ltd

Chase House 16 The Parks Trading Address: Lloyds British

Unit 1 kings Hill Business Park

Tel: 0121 506 4620

Newton-Le-Willows Merseyside WA12 0JQ Darlaston Road Wednesbury WS10 7SH Email: Sales@Lloydsbritish.com www.lloydsbritish.com

Registered Office: Chase House, 16 The Parks, Newton – Le – Willows, Merseyside WA12 OJQ Registered in England and Wales under no 6847930 VAT Reg No GB 151 6295 70